



BUTSURI-TANSA (Geophysical Exploration)	The Soc	iety of Exploration Go	eophysicists of	Japan E
Available Issues Japanese				Publisher Site
Author:	Keyword:		Search	ADVANCED
Add to Favorite Articles	e/Citation Alerts	Add to Favorite Publications	Register Alerts	? My J-STAGE HELP

<u>TOP</u> > <u>Available Issues</u> > <u>Table of Contents</u> > <u>Abstract</u>

ONLINE ISSN: 1881-4824 PRINT ISSN: 0912-7984

BUTSURI-TANSA(Geophysical Exploration)

Vol. 58 (2005), No. 6 pp.599-609

[Image PDF (2999K)] [References]

Slope failures due to heavy rainfall

Shinjuro Komata¹⁾

1) Nippon Koei co. LTD

(Manuscript received December 20, 2005) (Accepted January 11, 2006)

ABSTRACT Slope failures and debris flows due to heavy rainfall are frequent in Japan, which have damaged many lives and properties. They have occurred in this country under geological conditions prone to slope unstability, and under meteorological conditions such as typhoon, frontal rain and snowfall.

In this paper we have reviewed the mechanism of slope failures due to heavy rainfall, and introduce the knowledge and the technology especially in geophysical investigation about where and when slope failures occur due to heavy rainfall.

Key words: rainfall, slope failure, seepage flow, permeability, hydro-geomorphology, hydrogeology

[Image PDF (2999K)] [References]

Download Meta of Article[Help]

<u>RIS</u>

BibTeX

To cite this article:

Shinjuro Komata (2005): Slope failures due to heavy rainfall, BUTSURI-TANSA (Geophysical Exploration), **58**, 599-609.

doi:10.3124/segj.58.599

JOI JST.JSTAGE/segj/58.599

Copyright (c) 2007 The Society of Exploration Geophysicists of Japan









Japan Science and Technology Information Aggregator, Electronic JSTAGE

